


Fig-1

Fig-3



This exploded perspective view illustrates the assembly of a mechanical component 100. The assembly includes a base plate 10 with a central hole 26 and a flange 27. A shaft 28 is shown passing through the hole 26. A nut 76 is positioned to thread onto the shaft 28. A washer 24 is shown below the flange 27. A bracket 14 is shown with a hole 15 and a flange 20. A plate 60 is shown with a hole 66 and a flange 64. A washer 68 is shown below the flange 64. A bolt 70 is shown with a threaded section 74 and a hexagonal head 72. The assembly is shown in an exploded state, with arrows indicating the relative positions of the components.

1

Fig-4




Fig-5




Fig-6

